

IRIS Pro Server

[IRIS Pro Server Admin - Preferences](#)

[IRIS Pro Server - Monitor](#)

IRIS Pro Client

[Main Control Screen](#)

[Admin - General](#)

[Admin - Calibration Edit](#)

[Admin - Network Setup](#)

IRIS Server

Admin Log History Monitor

Contacts Zones Preferences E-Mail Text (SMS)

Update Zone Preferences More Commands ... Save

Client Admin - Incativity Auto Close

Auto close after 0 seconds (Select 0 to disable)

Network Alerts

Network Timeout 2.0 seconds

Network Alert buffer 5 minutes

Admin Password ☐ Show Admin Password in Alerts

Web Monitor

☐ Enabled

Select Network Location

Server - Password Required Functions

☐ Start ☐ Stop

Zone - Password Required Functions

☐ Admin ☐ Start ☐ Stop

Zone - Alert Acknowledgments

☐ Require Corrective Action

☐ Require Operator ID

Multi Zone Power Cycle Synchronization

☐ Enabled

Stop All Zones Monitor: OFF Wed - 7 Sep 2016 - 11:26:37 PM 192.168.2.199 V 4.02.01

IRIS Server

Admin

Log History

Monitor

Stop Monitor

Stop Zone(s)

Address	Name	Version	Shutdown Schedule	Calibration Date		Status
192.168.2.199	Zone 1	4.02.01		2016-09-07 23:23		Calibrate
192.168.2.200	Zone 2					Disabled

Today's System Log

Filter

Time	Message
07-Sep-16 23:27:49.47	Net:Monitor Started
07-Sep-16 23:27:49.44	Sys:IRIS Monitor Started
07-Sep-16 23:27:21.10	Net:Monitor Stopped
07-Sep-16 23:27:21.04	Sys:IRIS Monitor Stopped
07-Sep-16 23:27:05.04	Net:Monitor Started
07-Sep-16 23:27:05.03	Sys:IRIS Monitor Started
07-Sep-16 23:25:45.03	Server Started

Stop All Zones

Monitor: ON

Wed - 7 Sep 2016 - 11:27:59 PM

192.168.2.199

V 4.02.01

IRIS Client Main Control Screen

[Back to Top](#)

Admin

V4.02.01

Communication Port

< COM3 >

Test Port

Screen Size

☒ 800 x 480

☐ Full Screen

Passwords

☐ Admin

☐ Start Power Supply

☐ Stop Power Supply

Change Password

☐ Com Log Enabled

Save

Admin

Calibration

Network

Close

74

Last Calibration: 07-Sep-2016 11:23 PM V4.02.01

Power Timers		Sensor	Pos	Neg
Pos	< 5.0 >	☒ 1	< 15 >	< -15 >
Idle	< 1.0 >	☒ 2	< 10 >	< -10 >
Neg	< 5.0 >	☒ 3	< 5 >	< -5 >

☒ **Alerts Enabled**

Sensor Range ± < 5 >

Cycles < 10 >

KV AC < 8.0 > ± < 2.0 >

Total Min:Sec
01:50.0

Reset

Save

Admin Calibration Network Close

84

Wired Network Setup

V4.02.01

☒ Network Enabled

IP Address

192.168.2.199

MAC Address

24BE050198BA

Save

Admin

Calibration

Network

Close

81